

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2024

Submitted Date:

07/10/2024

Document Number:

696306503**FIELD INSPECTION FORM**Loc ID 429686 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429687	WELL	SI	04/19/2024	OW	123-35863	Antelope A-E-18HZ	SI
429689	WELL	SI	01/01/2024	OW	123-35865	ANTELOPE F-J-18HNB	SI
431877	WELL	SI	01/01/2023	OW	123-36836	Antelope K-O-18HNB	SI

General Comment:[This is a Well Pad and Tank Battery Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	F-J-18HNB Well Sign has faded no longer visible; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	08/09/2024
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Wellhead parts at F-J-18HNB Wellhead and unmarked 2" Riser; see photos		
Corrective Action:	Comply with Rule 606 Comply with Rule 1105	Date:	08/09/2024
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at A-E-18HZ Separator Site; see photos		
Corrective Action:	Comply with Rule 1105	Date:	08/09/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment: Panels			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Other	# 1		
Comment: TA Wellhead - F-J-18HNB			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Wellhead K-O-18HNB			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment: Electric Motors on Pumping Units			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment: Appear to be plumbed to surface			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 429687

Type: WELL

API Number: 123-35863

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment:

TA - Well appears to have been Plugged and Abandoned per Form 42 PA - 40378362 with a MIRU Date of 05.15.2024
Form 6N - 403747402 dated 04.29.2024
Form 27I - 403752263 dated 04.26.2024
Well has been Cut and Capped
No Form 6S on file yet

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 429689

Type: WELL

API Number: 123-35865

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Well found in TA Status

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431877

Type: WELL

API Number: 123-36836

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment:

SI - Since 01.01.2023

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine Field Inspection	petrie	07/10/2024
Unmarked Risers at F-J-18HNB Wellhead and A-E-18HZ Separator Site		
Unused Wellhead Parts at F-J-18HNB Wellhead		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306504	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617291