

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/10/2024

Document Number:

705000751**FIELD INSPECTION FORM**Loc ID 311447 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
311447	LOCATION	AC			-	DRY CREEK 13-35	EG
415210	WELL	SI	07/01/2021	OW	123-31010	DRY CREEK 23-35	PA
415232	WELL	SI	07/01/2021	OW	123-31018	DRY CREEK 35-35	PA
415233	WELL	SI	07/01/2021	OW	123-31019	DRY CREEK 11-35	PA
415246	WELL	SI	07/01/2021	OW	123-31022	DRY CREEK 14-35	PA
415247	WELL	SI	07/01/2021	OW	123-31023	DRY CREEK 13-35	PA

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 311447 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415210 Type: WELL API Number: 123-31010 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415232 Type: WELL API Number: 123-31018 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415233 Type: WELL API Number: 123-31019 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415246 Type: WELL API Number: 123-31022 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415247 Type: WELL API Number: 123-31023 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
(5) wells are plugged and abandoned; COGCC form 42 notices of start of plugging operations received March/ April 2024. On location flowlines have been removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #403842679 received 07/02/2024. On location dump and process flowlines at facility/ battery have been removed. No flowlines/ risers observed at PA well and tank battery/ equipment areas. Remediation work (historical) is in progress.	maclarej	07/10/2024
As outlined on COGCC form 19 spill report Doc #403838672 received on 06/27/2024: On June 27, 2024, historically impacted soil was discovered following cut and cap operations at the Dry Creek 11,23-35 wellhead locations. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	07/10/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000754	View of location at PA wells; to NE	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617792
705000755	View of location to SE; OOS GMR	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617793