

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/10/2024

Document Number:

713900770**FIELD INSPECTION FORM**Loc ID 318294 Inspector Name: Hansen, Logan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	
Arthur, Denise		denise.arthur@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241051	WELL	PR	07/01/2023	OW	123-08839	A L LUFT 2	RI

General Comment:

On 7/09/2024, Reclamation Specialist Logan Hansen conducted an Interim Reclamation and Stormwater inspection in response to a complaint by the surface owner at the KP Kauffman Company Inc A L Luft#2 Location.

The following compliance issues were observed during this inspection:

- 1) 606.c. Weeds
- 2) 1003.f. Noxious weeds

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	241051	Type:	WELL	API Number:	123-08839	Status:	PR	Insp. Status:	RI
Complaint									
Comment:	Complaint #: 403846337 Field Inspector Assigned: Logan Hansen Location ID: #318294 Inspection Document: #713900770 Nature of complaint: Complainant had concerns with excessive invasive weeds growing along the well location pad and access road as well as a dangerous bridge along the access road. The complaint was submitted 06/28/2024. ECMC staff will not be addressing the dangerous bridge as that would be considered a civil matter. During the inspection it was observed by ECMC staff that the access road had been mowed however Scotch thistle and Curly dock were observed still growing along the access road right of way. It was observed as well that Kochia and Curly dock have been left unmanaged across the well location, therefore the Operator shall control and manage all weeds and noxious weeds across the entirety of the location and access road.								
Corrective Action:	Operator will comply with Rule 606 and 1003.f to manage all weeds along the access road and at the well location.							Date:	07/17/2024
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of this inspection, no erosion issues were observed at the location or along the access road.

Operator shall continue to monitor and manage this site for stormwater run on and runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713900771	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617941