

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2024

Submitted Date:

07/10/2024

Document Number:

695109814

FIELD INSPECTION FORM

Loc ID 333411 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
SANCHEZ, ZEKE		zeke.sanchez@enrllc.com	Insp. w/ca's

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89168	WELL	TA	03/15/2021	GW	071-06747	GROSSO 13-17 TR	TA
217452	WELL	PR	10/15/1996	CBM	071-06229	GROSSO 13-17	PR

General Comment:

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:				Date: _____	
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
				corrective date	
Type: Gas Meter Run		# 1			
Comment:		CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:					Date:
Type: Bradenhead		# 2			
Comment:		BOTH ARE ACCESSABLE			
Corrective Action:					Date:
Type: Vertical Separator		# 2			
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked		# 8			
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment		# 2			
Comment:					
Corrective Action:					Date:
Type: Pump Jack		# 1			
Comment:		ORIGINAL WELL			
Corrective Action:					Date:
Venting:					
Yes/No		NO			
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	89168	Type:	WELL	API Number:	071-06747	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder:			
Comment:		LAST MIT MARCH 2024							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		08/23/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:		NONE	
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	217452	Type:	WELL	API Number:	071-06229	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		08/23/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		1		Fluid Type:		NONE	
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 112918Lat: 37.169855Long: -104.703449Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: Type: Produced WaterLined: NOPit ID: 112918Lat: 37.169855Long: -104.703449Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition:

Comment:		Date:
Corrective Action		
Anchor Trench Present: <u>NO</u> Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>YES</u>		
Comment:		Date:
Corrective Action		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695109815	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617924