

Inspection Photos
Location Name: UPRR 42 Pan Am D2
Location ID: 318931



Photo 1 wellsite.

Photo 2 WH.

Inspection Photos
Location Name: UPRR 42 Pan Am D2
Location ID: 318931



Photo 3 Sign.

Photo 4 ancillary equip.

Inspection Photos
Location Name: UPRR 42 Pan Am D2
Location ID: 318931



Photo 5 Pump jack.



Photo 6 Tank Battery.

Inspection Photos
Location Name: UPRR 42 Pan Am D2
Location ID: 318931



Photo 7 Tank Battery sign.

Photo 8 Unlined gravel berm around the tank battery not in compliance with Rule 603.o.

Inspection Photos
Location Name: UPRR 42 Pan Am D2
Location ID: 318931



Photo 9 Unlined gravel berm around the tank battery not in compliance with Rule 603.o.

Photo 10 Unlined gravel berm around the tank battery not in compliance with Rule 603.o.

Inspection Photos
Location Name: UPRR 42 Pan Am D2
Location ID: 318931



Energy & Carbon Management Commission
40.12895, -104.78159, 4902.9ft, 2°
07/10/2024 15:06:38



Energy & Carbon Management Commission
40.12905, -104.78106, 4915.5ft, 242°
07/10/2024 15:05:43

Photo 11 Unlined gravel berm around the tank battery not in compliance with Rule 603.o.

Photo 12 Horizontal heated separator.

Inspection Photos
Location Name: UPRR 42 Pan Am D2
Location ID: 318931



Photo 13 Gas Meter Run.