

Inspection Photos

Loc: 324494

Operator: **OXY USA INC**

Inspection Date: 7/9/2024

County: Huerfano



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the access road.. The access road will need to be decompacted and reclaimed. Previous corrective action has not been completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:324494 | Date: 7/9/2024

Inspection Photos



Photo 2. Facing south toward the location. The well has been plugged and abandoned . The location will must be reontoured back to the original contours and reclaimed. This gate does not prevent livestock entry.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:324494 | Date: 7/9/2024

Inspection Photos



Photo 3. Facing toward the wellsite. There is pipe riser that still remains on the location that must be removed per 1004 Rules.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:324494 | Date: 7/9/2024

Inspection Photos



Photo 4. Facing south toward the fill slope which must be recontoured back to the original condition. The four guyline anchors need to be removed along with the pipe riser shown in this photo.



Inspection Photos



Photo 5. There is a pile of roadbase that remains at the south side of the location that must be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:324494 | Date: 7/9/2024

Inspection Photos



Photo 6. Facing toward the abandoned well which was cut and capped. The remaining pipe riser must be removed.

