

# Inspection Photos

Loc: 334553

Operator: OXY USA INC

Inspection Date: 7/9/2024

County: HUERFANO



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east along the access road. Grading has been performed to allow drainage off the road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 334553 | Date: 7/9/2024



## Inspection Photos



**Photo 2.** Facing northeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 334553 | Date: 7/9/2024



## Inspection Photos



**Photo 3.** Facing northwest at the location. There is a pile of brush debris that was pushed to this area that must be removed. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 334553 | Date: 7/9/2024



## Inspection Photos



**Photo 4.** Facing toward the abandoned wellhead which has been backfilled with road base material.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 334553 | Date: 7/9/2024



## Inspection Photos



**Photo 5.** The plastic liner is compromised and impacted soil needs to be removed.

