

Inspection Photos

API: 055-06037

Operator: OXY USA INC

Inspection Date: 7/9/2024

County: HUERFANO



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. The perimeter fence around the location is not maintained and there is wire laying on the ground.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. The perimeter fence around the location is not maintained. Previous corrective action was not completed.

