

Inspection Photos

API: 055-06316

Operator: OXY USA INC

Inspection Date: 7/9/2024

County: HUERFANO



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. There is rock and soil pushed up along the road side. This is not an adequate stormwater control.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing southeast along the access road. There is rock and soil pushed up along the road side. This is not an adequate stormwater control.



Inspection Photos



Photo 3. There is sediment that has been transported offsite along the road. A BMP such as a sediment trap should be installed to control erosion.



Inspection Photos



Photo 4. Facing back north the steep grade of access road. Stormwater is not being diverted off the road which is causing erosion of the road. Stormwater should be divert toward red arrow and into a sediment trap.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06316 | Date: 7/9/2024

Inspection Photos



Photo 5. Facing north along the steep grade of access road. Stormwater is directed all the way down this road and there are no BMP's for sediment control.



Inspection Photos



Photo 6. Facing southwest along the access road near the SMU #1-12-B . Sediment has been deposited and pushed off the road into this area creating additional disturbance.

