

Inspection Photos
Location: State 3-8
Location ID: 314181
API # 05-099-06131



Photo 1 –Well Placard on meter house for State 3-8

Photo 2 – Meter house for State 3-8

Inspection Photos
Location: State 3-8
Location ID: 314181
API # 05-099-06131



Photo 3 – Tank Battery

Photo 4 – Tank Battery fencing not adequately maintained

Inspection Photos
Location: State 3-8
Location ID: 314181
API # 05-099-06131



Photo 5 – Unused piping in secondary containment for Tank Battery/ Secondary containment not adequate

Photo 6 – Placard is illegible

Inspection Photos
Location: State 3-8
Location ID: 314181
API # 05-099-06131




Photo 7 – Emergency Contact number illegible

Photo 8 – Door to separator house not attached to building

Inspection Photos
Location: State 3-8
Location ID: 314181
API # 05-099-06131



Photo 9 – Meter house leaning

Photo 10 – Unused undefined piping

Inspection Photos
Location: State 3-8
Location ID: 314181
API # 05-099-06131



Photo 11 – Unused undefined piping

Photo 12 – State 3-8 well placard

Inspection Photos
Location: State 3-8
Location ID: 314181
API # 05-099-06131



Photo 13 – State 3-8 Well and surrounding area