

Inspection Photos
Location: State 4-8
Location ID: 314190
API # 05-099-06191



Photo 1 – Well placard, Pumping unit

Photo 2 – Wellhead and unused equipment

Inspection Photos
Location: State 4-8
Location ID: 314190
API # 05-099-06191



Photo 3 – Oil Stains in pumping unit frame

Photo 4 – Pumping Unit base is corroded.

Inspection Photos
Location: State 4-8
Location ID: 314190
API # 05-099-06191



Photo 5 – Produced water Condensate tank

Photo 6 – Area of historical tank battery; Open Remediation # 32251

Inspection Photos
Location: State 4-8
Location ID: 314190
API # 05-099-06191



Photo 7 – Historical Tank Battery location

Photo 8 – Oil water mix on east end of tank battery

Inspection Photos
Location: State 4-8
Location ID: 314190
API # 05-099-06191



Photo 9 – Oil water mix

Photo 10 – Oil water mix flow path

Inspection Photos
Location: State 4-8
Location ID: 314190
API # 05-099-06191



Photo 11 – Oil water mix end of flow at the time of inspection

Photo 12 – Produced water tank. Placard is illegible