

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/11/2024

Document Number:

710500327**FIELD INSPECTION FORM**Loc ID 314181 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments8 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	Strachan Exploration
Reed, Shawn		Shawn@strachanexploration.com	
, Justin		Justin@strachanexploration.com	Strachan Exploration

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227805	WELL	PR	01/01/2018	GW	099-06131	STATE 3-8	EI

General Comment:This is an Environmental Inspection for the State 03-08 well location located in Prowers County, Colorado.

Location					
Lease Road:					
Type	Access				
comment:	Two Track Road trough pasture. There is a section of road located at Lat 38.153775; Long -102.480169 where it appears sand from the roadway was piled on the shoulders of the road. This area shows signs of wind erosion causing the sand to be blown across the adjacent field.				
Corrective Action:	Operator shall maintain loose soils in accordance with Rule 1002.f.				Date: 09/09/2024
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:	There is a sign located at the tank battery and at the wellhead.				
Corrective Action:					Date: _____
Good Housekeeping:					
Type	UNUSED EQUIPMENT				
Comment:	There are two pipes east of the meter run not being utilized near the tank battery.				
Corrective Action:	Comply with Rule 1101.a.(3).				Date: 08/15/2024
Type	WEEDS				
Comment:	Tank Battery Location. The surface equipment; meter house, separator and tank is surrounded by vegetation and weeds.				
Corrective Action:	Opertaor shall maintain weeds and vegetation in this area, Comply with Rule 606				Date: 08/15/2024
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: _____					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	TANK BATTERY				
Comment:	The fence surrounding the tank battery is in disrepair.				
Corrective Action:	Repair and maintain fence in accordance with Rule 603.h.				Date: 08/15/2024
Equipment:					
					corrective date
Type: Vertical Separator	# 1				
Comment:	Door to separator house is no longer attached to the building and is laying on the ground				
Corrective Action:	Operator shall inspect and maintain equipment in accordance with Rule 609				Date: 08/15/2024
Type: Gas Meter Run	# 1				
Comment:	Meter run is leaning and no longer supported on skid blocks.				
Corrective Action:	Anchor equipment ensuring anchors are engineered to ensure the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 607				Date: 08/15/2024
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS

	1	200 BBLs	STEEL AST		
Comment:	Tank Placards are illegible				
Corrective Action:	Install sign to comply with Rule 605.h.				Date: 08/15/2024
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate			Inadequate	
Comment:	Secondary Containment not maintained, Vegetation and weeds growing in Secondary Containment Berm				
Corrective Action:	Operator shall remove vegetation from secondary containment berms, Comply with Rule 606				Date: 08/15/2024
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 227805 Type: WELL API Number: 099-06131 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500331	Inspection # 710500327 Location Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619046