

Inspection Photos

Loc: 324498

Operator: **OXY USA INC**

Inspection Date: 7/9/2024

County: Huerfano



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road near the SMU #1-12-B . Sediment has been deposited and pushed off the road into this area creating additional disturbance.



Inspection Photos



Photo 2. Facing southwest along the access road. There is erosion that has occurred along the road. Red arrow points to shovel placed in the erosion channel.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324498 | Date: 7/9/2024

Inspection Photos



Photo 3. Facing northeast back down the access road. There are no BMP's to control erosion along this entire stretch of road



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:324498 | Date: 7/9/2024

Inspection Photos



Photo 4. Facing southwest along the access road. There is erosion that has occurred along the road which has no BMP's to control erosion.



Inspection Photos



Photo 5. Facing southwest further along the access road. There is more vegetation establishment but there is still erosion along the road. Stormwater should be diverted off the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324498 | Date: 7/9/2024

Inspection Photos



Photo 6. Facing southwest further along the access road. This culvert has filled in with sediment.



Inspection Photos



Photo 7. There is a pipe riser along the road with t-post.



Inspection Photos



Photo 8. Facing southwest further along the access road. There is a tree that fell over blocking the road. Could not go any further to the wellsite.



Inspection Photos



Photo 5. Facing southwest further along the access road. There are areas of erosion occurring which need to be repaired and stabilized.

