

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/11/2024

Document Number:

713601232**FIELD INSPECTION FORM**Loc ID 324498 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Oxy		ECMCInspections@Oxy.com	
Newville, Toni		toni_newville@oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324498	LOCATION	AC			-	DIKE MOUNTAIN UNIT- 628S70W 13SENW	RI

General Comment:

This is a follow up of the previous inspection (#713600302) at the Sheep Mountain Unit 4-13 location.
Unable to access the wellsite due to road erosion issues and fallen trees.
See attached photos and additional details within this report.

Location**Lease Road:**

Type	Access		
comment:	The access road is not maintained to allow safe vehicle access to the wellsite. There are areas of the road that are very steep with trees and large rocks fallen down along the road. Access roads must be maintained in in a stable condition to accommodate all weather access.		
Corrective Action	Comply with Rule 603.I.	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the access road and no BMP's have been installed since previous inspection. There is no diversion for stormwater which is directed down the entire portion of the road causing further erosion. Sediment is being deposited offsite and there are insufficient BMP's installed to prevent erosion. Areas of erosion must be repaired and stabilized. BMP's must be implemented in accordance with good engineering practice and must be maintained. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601234	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619278