

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2024

Submitted Date:

07/11/2024

Document Number:

707603007

## FIELD INSPECTION FORM

Loc ID 326884 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

## Operator Information:

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

## Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

## Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

## Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

## Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246016	WELL	PA	01/12/2022	OW	123-13812	EHRlich 2	PA

## General Comment:

This is a PLUGGED &amp; ABANDONED WELL / ABANDONED BATTERY inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Battery: Abandoned. ALL equipment has been removed.

Abandoned Battery SE corner GPS coordinates: 40.431926 / -104.582989

Abandoned Centralized Battery formerly served 2 Location IDs  
(326884, 326878).

(Well(s): 2: Plugged &amp; Abandoned | PA).

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Plunger Lift		# 0			
Comment:		Plugged & Abandoned   PA. Equipment removed.			
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 246016

Type: WELL

API Number: 123-13812

Status: PA

Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On WED 07/10/2024 at approximately 15:28 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: EHRLICH-65N64W/5SWNW Location ID: 326884 Well Name(s) &amp; API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.431926 / -104.582989</p> <p><b>WELL STATUS COMMENT:</b> Plugged &amp; Abandoned   PA. Form 6-SRA on file. Plugging, cut/cap date: 01/12/2022. Approved. Plugged &amp; Abandoned   PA well GPS coordinates: 40.429970 / -104.581060</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	07/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603008	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619336">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619336</a>