

Well Site Inspection

Date:07/09/2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 333124

Inspection Document #: 708201405

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Photo 1. Venting observed as bubbles in standing fluid at casing assembly.

Inspection Photos
Location Name: Nessu-Kinder #16
Location ID: 333124



Photo 2. Pump jack is disassembled.

Inspection Photos
Location Name: Nessu-Kinder #16
Location ID: 333124



Photo 3. Unused equipment observed outside of fenced portion. Also pictured, CO List B Noxious Weed (musk thistle) and undesirable vegetation (kochia and prickly lettuce) observed around the location.

Inspection Photos
Location Name: Nessu-Kinder #16
Location ID: 333124



Photo 4. Continued from Photo 3; unused equipment observed.

Inspection Photos
Location Name: Nessu-Kinder #16
Location ID: 333124



Photo 5. Unused equipment observed outside of fenced portions. Signage does not appear to have been updated to reflect the registered well name.

Inspection Photos
Location Name: Nessu-Kinder #16
Location ID: 333124



7/9/24, 2:24 PM
357° N
ECMC

Photo 6. CO List C Noxious Weed (canada thistle) observed to be growing in and around equipment and throughout the location.