

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/11/2024

Document Number:

708201406

FIELD INSPECTION FORMLoc ID 317831 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogcc@kpk.com	All Inspections
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240034	WELL	SI	04/01/2021	OW	123-07822	NESSU 15	SI
317831	LOCATION	AC			-	NESSU-62N66W 20NWSE	AC

General Comment:

On 07/09/2024, ECMC Staff conducted a field inspection in response to a reclamation complaint at the KP Kauffman Company Inc - Nessu #15 (API #123-07822). Refer to the Complaint Section of this Field Inspection Report for additional information.

The following compliance issues were observed during this inspection:

- 1) 606.c. Weeds
- 2) 1003.f. Noxious Weeds

Inspected Facilities

Facility ID: 240034 Type: WELL API Number: 123-07822 Status: SI Insp. Status: SI

Complaint

Comment: Complaint: #403846355
 Field Inspector Assigned: Dylan Edwardson
 Location ID: #317831
 Well API: #123-07822
 Inspection Document: #708201406
 Nature of complaint: Complainant had concerns that the location has noxious weeds taking over and spreading from the Nessu 15 well location. The complainant also stated that the Operator is not managing this location and the county is saying that the weedy vegetation needs to be managed.
 During this inspection, ECMC Staff observed that the well location appears to be overgrown with undesirable vegetation (kochia, curly dock and prickly lettuce) and CO List B Noxious Weed (musk thistle). It does not appear that weedy vegetation has been previously managed. Refer to attached inspection photos for additional.

Corrective Action: Operator will comply with Rule 606 and 1003.f to manage all weedy vegetation at the location.

Date: 07/18/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 317831 Type: LOCATION API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708201412	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619495