

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2024

Submitted Date:

07/11/2024

Document Number:

713301035

FIELD INSPECTION FORM

Loc ID 321282 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Silver, Randy	720-827-6688	randy.silver@state.co.us	
, CivitasResources		Inspections@civiresources.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206592	WELL	SI	11/01/2023	GW	013-06087	DAWSON 2-10	SI

General Comment:

[production site inspection](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type TANK BATTERY		
Comment:	post and wire		
Corrective Action:		Date:	
	Type SEPARATOR		
Comment:	post and wire		
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:

						corrective date
Type: Plunger Lift	# 1					
Comment:						
Corrective Action:				Date:		
Type: Bradenhead	# 1					
Comment:	piped to surface					
Corrective Action:				Date:		
Type: Horizontal Heated Separator	# 1					
Comment:						
Corrective Action:				Date:		
Type: Ancillary equipment	# 3					
Comment:	automation panels					
Corrective Action:				Date:		
Type: Gas Meter Run	# 1					

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 206592 Type: WELL API Number: 013-06087 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 09/28/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 73 Fluid Type: WATER AND GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>Routine inspection</u>	kesterm	07/11/2024
<u>This inspection does not nullify any orders or NOAV from the ECMC</u> <u>This is a continuing education inspection</u>		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301036	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619849