

Inspection Photos

API: 055-06012

Operator: OXY USA INC

Inspection Date: 7/9/2024

County: HUERFANO



Inspection Photos



Photo 1. Facing southwest at the location.



Inspection Photos



Photo 2. Facing toward the produced water tank. The secondary berm around the tank is insufficient to contain a spill. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 7/9/2024

Inspection Photos



Photo 3. Facing west at the backside of the tank. The secondary containment at the tank is insufficient to contain a spill. The red arrow points to a culvert that would allow a potential spill to flow all the way toward the southwest portion of the pad near the perennial stream.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 7/9/2024

Inspection Photos



Photo 4. The remediation area where tank was located has been backfilled with sand and gravel. The red arrow points to a culvert that would allow a potential spill to flow all the way toward the southwest portion of the pad



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 7/9/2024

Inspection Photos



Photo 5. Wattles were installed along the southeast side but stop at this point. The red arrow points to a culvert that would allow a potential spill to flow all the way toward the southwest portion of the pad.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 7/9/2024

Inspection Photos



Photo 6. Facing toward the southwest portion of the pad.



Inspection Photos



Photo 7. Facing southeast at the down gradient portion of the location. There is a creek approximately 10ft' from the edge of the location shown at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 7/9/2024

Inspection Photos



Photo 8. The perimeter fence at the west side of the location still remains in disrepair.



Inspection Photos



Photo 9. Standing approximately 125' west of the location along the flowline area is an eroded out culvert where the creek flows. The culvert needs repaired or removed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 7/9/2024

Inspection Photos



Photo 10. Facing southeast toward the location. There is a pile of orange cones and fencing at this area that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources