

# Inspection Photos

07/11/2024

**Operator:** UTAH GAS OP LTD DBA UTAH GAS  
CORP - 10539

**Location ID:** 322443

**Inspection Doc:** 696205971

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 1:** Photos taken from the central areas of the Location. Photos provide an overview of the Location facing north, east, south and west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 3:** Photos 3-4 example showing Undesirable and Noxious Plant establishment observed throughout the Location; Species include Canada thistle, Bull thistles, Houndstongue, Field Bindweed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 4:** See comments under photo 3.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 5:** Photo example showing fence along the perimeter of the Location has not been maintained.



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 6:** Photos 6-9 taken from the access road leading to the Location. Photos examples showing reclamation including, but not limited to, compaction alleviation, recontouring/regrading and revegetation have not been performed in accordance with 1004 Rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 7:** See comments under photo 6.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 8:** See comments under photo 6. Photo taken from the cut slopes of the access road. Vegetation along road is predominantly undesirable plant species including Houndstongue and Bull thistle as seen within this photo.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 322443



**Photo 9:** See comments under photo 6. Photo taken from the access road. Vegetation along road is predominantly undesirable plant species including Canada thistle as seen within this photo.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources