

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/03/2024

Submitted Date:

07/15/2024

Document Number:

717000013**FIELD INSPECTION FORM**Loc ID 320361 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203547	WELL	TA	03/30/2021	GW	001-09107	BOX ELDER 1	TA

**General Comment:**[Routine Inspection](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment.		
Corrective Action:	Within the designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 7/31/2024 days. See attached photo # 4 - 5 - 6 - 7 & 8.		Date: 07/31/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		39.901871,-104.602896	
Comment:	Rule 425 Visual Impact Mitigation (Graffiti)					
Corrective Action:	Production facility is clearly visible from a public highway, road, or publicly-maintained trail. Facility paint is not uniform, non-contrasting, non-reflective color tones (similar to the Munsell Soil Color Coding System), and with colors matched to but slightly darker than the surrounding landscape. Paint production facilities per Rule 425. Corrective Action Date 9/13/2024 days. See attached photo # 5 - 6 - 7 & 8.				Date:	09/13/2024

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

AirsID

API Number
001-09107

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

--	--	--	--

Inspected Facilities

Facility ID: 203547

Type: WELL

API Number: 001-09107

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment: TA

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/30/2023

Annual Brhd Completed?

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: None

End Surf Csg Pressure: --

Comment: Appeared to be plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>CECMC Inspection Report Summary</div> <div>On Wednesday July 3rd at approximately 11:35am. I, Inspector Chane Finkenbinder, conducted an on-site inspection.</div> <div>Operator: Kerr-McGee</div> <div>Location name: BOX ELDER 1</div> <div>API #001-09107</div> <div>Location ID #: 320361</div> <div>County: Adams</div> <div>While there, I observed a shut in well.</div> <div>During this inspection the following possible compliance issues were observed:</div> <div>Rule 606: Weeds, dead weeds, trash, debris &amp; unnecessary / unused equipment. Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 7/31/2024 days. See attached photo # 4 - 5 - 6 - 7 &amp; 8.</div> <div>Rule 425 Visual Impact Mitigation (Graffiti) - Production facility is clearly visible from a public highway, road, or publicly-maintained trail. Facility paint is not uniform, non-contrasting, non-reflective color tones (similar to the Munsell Soil Color Coding System), and with colors matched to but slightly darker than the surrounding landscape. Paint production facilities per Rule 425. Corrective Action Date 9/13/2024 days. See attached photo # 5 - 6 - 7 &amp; 8.</div> <div>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</div> <div>This is a summary of inspection report.</div>	finkenbc	07/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000014	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6623367">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6623367</a>