

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2024

Submitted Date:

07/15/2024

Document Number:

717000015**FIELD INSPECTION FORM**Loc ID 320469 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256059	WELL	PR	10/11/2010	OW	001-09397	LINNEBUR 6-13	PR

General Comment:

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:		adequate			
Corrective Action:					Date: _____
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					corrective date
Type: Ancillary equipment		# 1			
Comment:					
Corrective Action:					Date:
Type: Pump Jack		# 1			
Comment:					
Corrective Action:					Date:
Type: Emission Control Device		# 1			
Comment:					
Corrective Action:					Date:
Type: Bird Protectors		# 2			
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked		# 4			
Comment:					
Corrective Action:					Date:
Type: Vertical Heated Separator		# 1			
Comment:					
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLs			39.826268,-104.151613	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Wells Served By Facilities Above</u>						
API Number		AirsID				
001-09397						
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	256059	Type:	WELL	API Number:	001-09397	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:		04/03/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		44		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:		Appeared to be plumbed to the surface							
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment						User		Date	
Routine Inspection						finkenbc		07/15/2024	
Attached Documents									
You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:									
Document Num	Description	URL							
717000016	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6623368							