

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/08/2024

Submitted Date:

07/09/2024

Document Number:

696205961

FIELD INSPECTION FORM

Loc ID 323800 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		andrewolson@chevron.com	
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210835	WELL	PA	08/08/2014	CBM	045-06593	CHEVRON SHALE 1-25A CHEVRON	RI

General Comment:

On 7/8/2024, Reclamation Specialist Trujillo conducted a final reclamation inspection at Chevron Usa Inc's CHEVRON SHALE #1-25A CHEVRON location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:
-1004 Final Reclamation.

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 210835 Type: WELL API Number: 045-06593 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment [Topsoil on Location has not been replaced, is predominantly bare, and has not been protected pursuant to Rule 1002.c.](#)

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control **Fail**

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present **Fail** Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: _____ Date _____

Comply with Rule 1004.a and conduct reclamation on the Location and access road including, but not limited to, recontouring/regrading, replacement of topsoil and revegetation activities. Ensure erosion controls are implemented to stabilize the seeded soil pursuant to Rule 1002.f. Comply with Rule 1004.e and 606.c and perform ongoing weed management; Oil and Gas Locations will be kept free of all Undesirable Plant Species.

Continue to monitor and manage the Location; ongoing stormwater and weed management required until the site receives a passing final reclamation inspection.

Overall Final Reclamation **Fail** Well Release on Active Location Multi-Well Location

ECMC Comments

Comment	User	Date
<p>Form 6(s) #400682542 states well was P&Ad 8/8/2014.</p> <p>On Operator submitted Form 4 #401407509 stating "Final Reclamation was complete".</p> <p>Inspection #692400010 observed that final reclamation of the Location has not been performed in accordance with 1004 Rules:</p> <p>"Location & Access Road have not been re-contoured & reclaimed. Debris and facilities have been removed. Operator indicated that Pad area had been seeded after Well was PA'd. Portions of site have good establishment of perennial vegetation though pad area remains compacted & areas are bare or sparsely vegetated. Tops of Berms (which may be topsoil) around site are not revegetated & appear to be used for livestock access & loafing areas. This site shows most pronounced Cut slope & has largest compacted, unvegetated area of the 3 Locations visited. Weed, Mullein established on site shows evidence of having controls applied".</p> <p>Inspection required Operator to comply with 1004 Rules.</p> <p>It was observed in this inspection that the Location remains out of compliance with ECMC Rules and Corrective actions: Location and access road have not been recontoured/regradad, and reclaimed in accordance with Rule 1004.a. Cut and fill slopes remain apparent. Additionally, topsoil remains bare and stockpiled on the north, west and southeastern ends of the Location, and has not been replaced. Undesirable Plant Species (Mullein) have continued to establish and spread on the Location and access road.</p> <p>This corrective action per #692400010 has not been addressed and remains applicable.</p>	trujilloam	07/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403849087	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616286
696205963	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616282