

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

07/09/2024

Document Number:

709100337**FIELD INSPECTION FORM**Loc ID 317042 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 75000Name of Operator: BYRD* CAROL W TRUSTEE OF CAROL W BYRDAddress: 8163 E 131 RDCity: WETUMKA State: OK Zip: 74883-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
Carol Byrd		cwbyrd@oilandgasroyalties.com	
Krystal Heibel		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234894	WELL	PR	12/05/1995	OW	121-07036	LYLE CHANDLER 1	EI
317042	LOCATION	AC			-	LYLE CHANDLER-62N49W 10NESE	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:			Hydrocarbons observed leaking from wellhead and around polish rod.	
Corrective Action:			Control and contain spills/releases and clean up per Rule 912.a.	Date: 07/26/2024
Crude Oil	Pump Jack			
Comment:			Hydrocarbon impacted soils next to pumping unit.	
Corrective Action:			Control and contain spills/releases and clean up per Rule 912.a.	Date: 07/26/2024

In Containment: No

Comment:

☒ Multiple Spills and Releases?

Equipment:

Type:	#		corrective date
Comment:		Wildlife protections devices not adequate around secondary containment.	
Corrective Action:		Install or repair wildlife protection equipment.	Date: 07/19/2024

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Date Run: 7/16/2024 Doc [#709100337]

Page 2 of 3

Inspected Facilities				
Facility ID: 234894	Type: WELL	API Number: 121-07036	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 317042	Type: LOCATION	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403849386	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616588
709100338	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6616579