

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2024

Submitted Date:

07/16/2024

Document Number:

707801022**FIELD INSPECTION FORM**Loc ID 324665 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All inspections
Burn, Diana		diana.burn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212300	WELL	IJ	07/01/2023	ERIW	057-06193	MCCALLUM UNIT 106	IJ

**General Comment:**

5 year MIT

**Inspected Facilities**Facility ID: 212300 Type: WELL API Number: 057-06193 Status: IJ Insp. Status: IJ**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
(e.g. 30 psig or -30" Hg) Inj Zone: PRREB

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 07/09/2019

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: 5 Year Tbg psi: 580 Csg psi: 840 BH psi: 0Insp. Status: Fail Leak Type: \_\_\_\_\_Comment: Casing at 0 psi at start of test pressured up to 840 psi 5 min 795 psi 10 min 750 psi loss of 90 psi test failedCorrective Action: S/I well and contact engineering with in 24 hours Date: 07/17/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<u>MIT failed within first 10 minutes</u>	<u>ramseys</u>	<u>07/16/2024</u>

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>707801030</u>	<u>Photo log</u>	<u><a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6624789">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6624789</a></u>