



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
07/10/2024
Submitted Date:
07/10/2024
Document Number:
697009702

Loc ID
443694

Inspector Name:
Peterson, Tom

On-Site Inspection ☐
2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:
30 Number of Comments
1 Number of Corrective Actions
☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443667	WELL	PR	06/01/2022	OW	123-42322	Spaur 10T-201	PR
443668	WELL	PR	06/01/2022	OW	123-42323	Spaur 10Q-241	PR
443669	WELL	PR	06/01/2022	OW	123-42324	Spaur 10i-201	PR
443670	WELL	PR	06/01/2022	OW	123-42325	Spaur 10Y-241	PR
443671	WELL	PR	06/01/2022	OW	123-42326	Spaur 10Q-401	PR
443672	WELL	PR	06/01/2022	OW	123-42327	Spaur 10L-241	PR
443673	WELL	PR	06/01/2022	OW	123-42328	Spaur 10i-321	PR
443674	WELL	PR	06/01/2022	OW	123-42329	Spaur 10L-321	PR
443675	WELL	PR	06/01/2022	OW	123-42330	Spaur 10L-421	PR
443677	WELL	PR	07/01/2022	OW	123-42331	Spaur 10L-301	PR
443679	WELL	PR	06/01/2022	OW	123-42332	Spaur 10Q-321	PR
443680	WELL	PR	07/01/2022	OW	123-42333	Spaur 10L-201	PR
443683	WELL	PR	06/01/2022	OW	123-42334	Spaur 10T-321	PR
443684	WELL	PR	06/01/2022	OW	123-42335	Spaur 10T-241	PR
443685	WELL	PR	06/01/2022	OW	123-42336	Spaur 10T-301	PR
443687	WELL	PR	06/01/2022	OW	123-42337	Spaur 10T-421	PR

General Comment:

This is a routine inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Date Run: 7/17/2024 Doc [#697009702]

Page 1 of 12

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 16		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol and chemical systems		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash has been dumped on location, see attached photo.		
Corrective Action:	Comply with Rule 606	Date:	07/26/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel x 16		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Panel x 14		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Soundwalls at compressors		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	Automation arrays, solar arrays, ECD scrubbers, genset, supplied air system, methanol and chemical systems in secondary containment, bulk lube oil storage in secondary containment with wildlife protections, bulk methanol storage in secondary containment.		
Corrective Action:			Date:
Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:			Date:
Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 4		
Comment:	Natural gas engines on compressors and VRU's.		
Corrective Action:			Date:
Type: Bradenhead	# 16		
Comment:	Bradenhead valves are exposed at surface		
Corrective Action:			Date:
Type: Flow Line	# 16		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 14		
Comment:	Pilots are on		

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	PBV FIBERGLASS		,
Comment: 210 bbls					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	16	OTHER	STEEL AST		,
Comment: 538 bbls					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 443667	Type: WELL	API Number: 123-42322	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 02/13/2023	Annual Brhd Completed? No		
Last Brhd Test Results	Initial Surf Csg Pressure: 6	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 443668	Type: WELL	API Number: 123-42323	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 07/11/2023	Annual Brhd Completed? Yes		
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 443669	Type: WELL	API Number: 123-42324	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 07/11/2023	Annual Brhd Completed? Yes		
Last Brhd Test Results	Initial Surf Csg Pressure: 7	Fluid Type: WATER H2O	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 443670	Type: WELL	API Number: 123-42325	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 02/13/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 3	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443671	Type: WELL	API Number: 123-42326	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR	
Corrective Action:	Date:

BradenHead			
Date of Last Brhd Test: 02/13/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443672	Type: WELL	API Number: 123-42327	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR	
Corrective Action:	Date:

BradenHead			
Date of Last Brhd Test: 07/11/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 3	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443673	Type: WELL	API Number: 123-42328	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR	
Corrective Action:	Date:

BradenHead			
Date of Last Brhd Test: 07/11/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443674	Type: WELL	API Number: 123-42329	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR			
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 07/11/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 3	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443675	Type: WELL	API Number: 123-42330	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR			
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 07/11/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443677	Type: WELL	API Number: 123-42331	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR			
Corrective Action:		Date:	

--	--	--	--

BradenHead

Date of Last Brhd Test: 07/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443679 Type: WELL API Number: 123-42332 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443680 Type: WELL API Number: 123-42333 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443683 Type: WELL API Number: 123-42334 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443684 Type: WELL API Number: 123-42335 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443685 Type: WELL API Number: 123-42336 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 443687 Type: WELL API Number: 123-42337 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead			
Date of Last Brhd Test: 01/16/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results	Initial Surf Csg Pressure: 366	Fluid Type: GAS	
	End Surf Csg Pressure: 0		
Comment:	<div></div>		
Corrective Action:	<div></div>	Date: <div></div>	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 7/10/2024 at approximately 09:05 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Spaur 4N67W 10 LQ location #443694 in Weld County, Colorado.</p> <p>While there, I observed trash on location. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 7/26/2024. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	07/10/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403849980	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617301
697009703	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617293