

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/10/2024

Submitted Date:

07/10/2024

Document Number:

696306507

**FIELD INSPECTION FORM**

Loc ID 310865 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 8960  
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
 Address: 555 17TH STREET SUITE 3700  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297461	WELL	TA	05/06/2019	GW	123-27152	ANTELOPE 21-18	TA

**General Comment:**

[Follow-Up Inspection to FIR 696305364 dated 10.26.2023](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access Road inaccessible - Hot Wire installed at Lease Road Entrance - no drop lines to access Lease Road or Wells		
Corrective Action:	Provide Key, Combinations and/or Alternate method of Access to Comply with Rule 204	Date:	07/26/2024

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 297461 Type: WELL API Number: 123-27152 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA - Since 05.06.2019  
MIT - 04.20.2020  
Form 6A - 403213997 with a Plug Due Date of 12.31.2029

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Lease blocked by Hot Wire</a>	petrie	07/10/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403850063	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617399">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617399</a>
696306508	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617398">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6617398</a>