

Inspection Photos

Loc: 485654

Operator: BNL (ENTERPRISE) INC

Inspection Date: 7/16/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the access road. The sides of the road will need to be reclaimed. The road has been regraded and crowned since previous inspection.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:485654 | Date: 7/16/2024

Inspection Photos



Photo 2. The culvert outlet has been repaired and outlet protection was installed, The loose soil along the embankment need to be stabilized..



Photo 3. The embankment along the road side at the culvert is not stabilized and loose gravel is falling into the culvert.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing northwest toward the access road. The side of the road needs to be seeded and stabilized. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:485654 | Date: 7/16/2024

Inspection Photos



Photo 4. Facing west toward the location. Sign posted at entrance.



Inspection Photos



Photo 5. Facing southwest at the location. The silt fence is not maintained.



Inspection Photos



Photo 6. Facing toward the soil stock pile. The topsoil has not been seeded and stabilized and weeds are beginning to establish.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:485654 | Date: 7/16/2024

Inspection Photos



Photo 7. Facing toward the drilled well which has a steel grate to prevent wildlife entry.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:485654 | Date: 7/16/2024

Inspection Photos



Photo 8. Facing southeast along the fill slope. There is erosion occurring shown at red arrow.



Inspection Photos



Photo 9. Southwest side of the location facing east. The silt fence is down and not maintained.



Inspection Photos



Photo 10. There is unused pipe stored at the east side of the location that must be removed.

