

Inspection Photos
Location: RMF Consolidation Line
Facility ID: 480127



Photo 1 – Fencing surrounding the excavation

Photo 2 –



Inspection Photos
Location
Facility ID:



Photo 3 –

Photo 4 – Excavation and weeds

Inspection Photos

Location

Facility ID:



Photo 5 – Excavation and weeds

Photo 6 – Excavation and weeds



Inspection Photos

Location

Facility ID:



Photo 7 – Storage of piping onsite

Photo 8 – Weeds



Inspection Photos

Location

Facility ID:



Photo 9 – Weeds and compromised liner



Photo 10 – Weeds and compromised liner



Inspection Photos

Location

Facility ID:



Photo 11 –



Photo 12 – Weeds and compromised liner



Inspection Photos

Location

Facility ID:



Photo 13 – Weeds and compromised liner

Photo 14 – Stockpile runoff of the liner

