

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2024

Submitted Date:

07/17/2024

Document Number:

713900779

FIELD INSPECTION FORM

Loc ID 330347 Inspector Name: Hansen, Logan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437331	WELL	AL	11/11/2015	LO	123-39488	ACORD 38C-29HZ	RI
437332	WELL	AL	11/11/2015	LO	123-39489	ACORD 39C-29HZ	RI
437333	WELL	AL	12/07/2015	LO	123-39490	ACORD 39N-29HZ	RI
437334	WELL	AL	11/11/2015	LO	123-39491	ACORD STATE 34N-30HZ	RI
437335	WELL	AL	11/11/2015	LO	123-39492	ACORD 13C-30HZ	RI
437336	WELL	AL	12/07/2015	LO	123-39493	ACORD 33N-30HZ	RI

General Comment:

This is a Final Reclamation Inspection for abandoned wells on a plugged and abandoned well location.

Inspected Facilities

Facility ID: 437331 Type: WELL API Number: 123-39488 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 437332 Type: WELL API Number: 123-39489 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 437333 Type: WELL API Number: 123-39490 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 437334 Type: WELL API Number: 123-39491 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 437335 Type: WELL API Number: 123-39492 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 437336 Type: WELL API Number: 123-39493 Status: AL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation	Pass	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input checked="" type="checkbox"/>
---------------------------	------	--	---

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713900780	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6626224