

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/11/2024

Document Number:

708201403**FIELD INSPECTION FORM**Loc ID 305848 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@oxy.com	All Inspections
Arthur, Denise		denise.arthur@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282859	WELL	SI	10/01/2021	GW	123-23565	WARNER 4-18	SI
305848	LOCATION	AC			-	WARNER-62N65W 18NWNW	AC

General Comment:

On 07/09/2024, ECMC Staff conducted a field inspection in response to a reclamation complaint at the Kerr McGee Oil & Gas Onshore LP - Warner #4-18 (API #123-23565). Refer to the Complaint and Location Section of this Field Inspection Report for additional information.

The following compliance issues were observed during this inspection:

1) 606.c. Weeds

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	WEEDS			
Comment:	Undesirable vegetation (kochia) was observed near the wellhead location and at potholes from flowline removal. Refer to attached inspection photos.			
Corrective Action:	Comply with Rule 606 and manage weedy vegetation.			Date: 07/19/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	282859	Type:	WELL	API Number:	123-23565	Status:	SI	Insp. Status:	SI
Complaint									
Comment:	<p>Complaint: #403846335 Field Inspector Assigned: Dylan Edwardson Location ID: #305848 Well API: #123-23565 Inspection Document: #708201403 Nature of complaint: Complainant has concerns that the Warner 4-18 has been abandoned and neglected with storage of oil and gas parts and noxious weeds within the fenced area. Complainant also stated that flowlines were removed 3 years ago and that the potholes have not been reclaimed, as such, the potholes are creating issues with their farming equipment. It was also stated that the two track access road is no longer visible and the complainant doesn't want a new two track access road in the hay filed because the old one can't be seen.</p> <p>At the time of this inspection, Staff observed that subsidence is occurring around the former potholes used for flowline removal and that both the well location and flowline potholes have evidence of undesirable vegetation (kochia) and non-uniform vegetation cover. The Warner 4-18 (API 123-23565) has been placed on a Form 6A Out of Service Designation list (doc #403108165) with a plugging due date of 12/31/2030. ECMC Staff contacted Operator representatives (D. Stromo and J. Brady) who indicated to Staff that the Warner 4-18 well will be placed on a plugging and abandonment list for a future date in Q3/Q4 of 2024. Undesirable vegetation will be addressed under "Good Housekeeping" section and the Operator shall coordinate with the affected surface owner to resolve subsidence observed along flowline potholes prior to P&A activities. Refer to attached inspection photos for additional information.</p>								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	305848	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Attached Documents									
You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:									
Document Num	Description	URL							
403852156	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619682							
708201413	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619681							