

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2024

Submitted Date:

07/11/2024

Document Number:

708201406

**FIELD INSPECTION FORM**

Loc ID 317831 Inspector Name: Edwardson, Dylan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 ECMC Operator Number: 46290  
 Name of Operator: KP KAUFFMAN COMPANY INC  
 Address: 1700 LINCOLN ST STE 4550  
 City: DENVER State: CO Zip: 80203

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Arthur, Denise		denise.arthur@state.co.us	
Watzman, Ross	303-825-4822	rwatzman@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240034	WELL	SI	04/01/2021	OW	123-07822	NESSU 15	SI
317831	LOCATION	AC			-	NESSU-62N66W 20NWSE	AC

**General Comment:**  
 On 07/09/2024, ECMC Staff conducted a field inspection in response to a reclamation complaint at the KP Kauffman Company Inc - Nessu #15 (API #123-07822). Refer to the Complaint Section of this Field Inspection Report for additional information.  
 The following compliance issues were observed during this inspection:  
 1) 606.c. Weeds  
 2) 1003.f. Noxious Weeds

**Inspected Facilities**

Facility ID: 240034 Type: WELL API Number: 123-07822 Status: SI Insp. Status: SI

**Complaint**

Comment: **Complaint: #403846355**  
 Field Inspector Assigned: Dylan Edwardson  
 Location ID: #317831  
 Well API: #123-07822  
 Inspection Document: #708201406  
 Nature of complaint: Complainant had concerns that the location has noxious weeds taking over and spreading from the Nessu 15 well location. The complainant also stated that the Operator is not managing this location and the county is saying that the weedy vegetation needs to be managed.  
  
 During this inspection, ECMC Staff observed that the well location appears to be overgrown with undesirable vegetation (kochia, curly dock and prickly lettuce) and CO List B Noxious Weed (musk thistle). It does not appear that weedy vegetation has been previously managed. Refer to attached inspection photos for additional.

Corrective Action: **Operator will comply with Rule 606 and 1003.f to manage all weedy vegetation at the location.** Date: 07/18/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 317831 Type: LOCATION API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403852071	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619500">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619500</a>
708201412	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619495">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619495</a>