

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2024

Submitted Date:

07/09/2024

Document Number:

713301027

FIELD INSPECTION FORM

Loc ID 318413 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

Findings:

- 10 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241253	WELL	SI	01/01/2024	GW	123-09041	UPRR 43 PAN AM I 21	SI

General Comment:

[Follow up inspection](#)

Location

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: [good](#)

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: [safety guards](#)

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead # 1

Comment: [piped to surface](#)

Corrective Action:

Date:

Type: Ancillary equipment # 2

Comment: [eletrical panels](#)

Corrective Action:

Date:

Type: Prime Mover #

Comment: [removed/missing](#)

Corrective Action: [Comply with Rule 606](#)

Date: [03/14/2024](#)

Type: Pump Jack # 1

Comment: [out of service with no prime mover](#)

Corrective Action: [Comlpy with Rule 606](#)

Date: [03/14/2024](#)

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241253 Type: WELL API Number: 123-09041 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 10/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Inspector Michael Kester, conducted Follow up on-site inspection as per Doc 713300771 Location: UPRR 43 PanAm I 21 Operator: KPK API#: 123-09041 County: Weld While there, I observed well site with pumping unit, During this inspection, the following possible compliance issues were observed: Unused equipment, Rule 606, corrective action date 3-14-2024 Mechanical Issues, Rule 608e, corrective action date 3-14-2024 Weather conditions: sunny and dry</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	07/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403852180	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619851
713301028	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6619845