

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/12/2024

Document Number:

713601239**FIELD INSPECTION FORM**Loc ID 324493 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Oxy		ECMCInspections@Oxy.com	
Sanchez, Chris		chris.sanchez@state.co.us	
Newville, Toni		toni_newville@oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324493	LOCATION	AC			-	GARCIA-627S70W 35NESE	RI

General Comment:

This is a follow up of the previous reclamation inspections (#690204276, #713600047, #713600952).
 The previous inspection corrective actions have not been entirely addressed.
 Operator is directed to perform all outstanding corrective actions immediately.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Recent noxious weed control was performed.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	The dilapidated snow fences were removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	The fencing is still down at the west side of the location. It appears repairs were made but additional work needs to be completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	1000 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Sufficent		Inadequate	
Comment:	The secondary containment of the tank is not adequate to contain a spill. The design allows a spill to flow thru a culvert to the west toward the perennial stream at the southwest corner of the location. It is advised that secondary containment be constructed per Rule 603.o. with steel containment and liner. There have been previous spills that have occurred and secondary containment must be properly installed for potential spill containment. Previous corrective action has not been completed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o Comply with Rule 902.b. for pollution prevention.				Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There have been wattles installed at the southeast side of the pad however the area of concern is along the southwest area near the perennial creek. The slope of the location is directed towards the creek and there are insufficient BMP's installed. Additionally there is an eroded out culvert where the creek flows approximately 125' northwest of the location along the flowline which needs to be repaired. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403852546	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6620156
713601240	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6620155