

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2024

Submitted Date:

07/19/2024

Document Number:

707801031**FIELD INSPECTION FORM**Loc ID 324459 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dillain Gage		dillain.gage@oxbow.com	
Energy, Gunnison		geops@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211688	WELL	PR	10/01/2021	GW	051-06010	FEDERAL 10-90-32	PR

General Comment:**ECMC Inspection Report Summary**

On Wednesday 7/10/2024, I, Inspector Scott Ramsey, conducted an inspection on site in response of Complaint document # 403831397 at Gunnison Energy Fed 10-90-32, at Location # 324459 in Colorado.

While there, I observed location was shut in. I took optical gas imaging of all equipment on location and could not find any evidence of venting through out location.

This is a summary of inspection report.

Inspected Facilities									
Facility ID:	211688	Type:	WELL	API Number:	051-06010	Status:	PR	Insp. Status:	PR
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Well shut in at time of inspection."/>									
Corrective Action: <input type="text"/> Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: Clear Temperature: 82 (F)Assisting Staff: Dusty Popejoy Camera #: _____☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
12:00	PM	13:00	PM

Equipment
Separation Equipment
Oil Tank(s)
Wellhead(s)

Comment: Optical gas imaging of all equipment on location and could not find any evidence of ventingCorrective
Action:

Date:

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801032	OGI video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6632488
707801033	OGI video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6632489
707801034	OGI video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6632490
707801035	OGI video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6632491