

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2024

Submitted Date:

07/22/2024

Document Number:

713301053

FIELD INSPECTION FORM

Loc ID 452217 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Silver, Randy	720-827-6688	randy.silver@state.co.us	
, KerrMcGee	970-515-1500	ECMCInspections@Oxy.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452259	WELL	PR	05/26/2021	OW	123-45493	YELLOWHAMMER 34N-17HZ	PR
452260	WELL	PR	05/26/2021	OW	123-45494	YELLOWHAMMER 4C-8HZ	PR
452261	WELL	PR	05/26/2021	OW	123-45495	YELLOWHAMMER 13N-17HZ	PR
452263	WELL	PR	05/26/2021	OW	123-45497	YELLOWHAMMER 30N2-8HZ	PR
452264	WELL	PR	05/26/2021	OW	123-45498	YELLOWHAMMER 34C-17HZ	PR
452266	WELL	PR	05/26/2021	OW	123-45500	YELLOWHAMMER 30N-8HZ	PR

General Comment:

[well site inspection](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	good, six wells		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric/automation disconnect panels		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Ancillary equipment	# 9		
Comment:	automation/electric panels		
Corrective Action:		Date:	
Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 6		
Comment:	Bradenheads from three wells tied into one messco unit Yellowhammer 13N-17Hz Yellowhammer 34N-17Hz Yellowhammer 34C-17Hz		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 452259 Type: WELL API Number: 123-45493 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/18/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: Bradenheads from three wells tied into one messco unit
Yellowhammer 13N-17Hz
Yellowhammer 34N-17Hz
Yellowhammer 34C-17Hz

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452260 Type: WELL API Number: 123-45494 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 43 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452261 Type: WELL API Number: 123-45495 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/18/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: Bradenheads from three wells tied into one messco unit
Yellowhammer 13N-17Hz
Yellowhammer 34N-17Hz
Yellowhammer 34C-17Hz

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452263	Type: WELL	API Number: 123-45497	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452264	Type: WELL	API Number: 123-45498	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/10/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Bradenheads from three wells tied into one messco unit

Yellowhammer 13N-17Hz
 Yellowhammer 34N-17Hz
 Yellowhammer 34C-17Hz

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452266	Type: WELL	API Number: 123-45500	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/05/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 28 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine inspection	kesterm	07/22/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301054	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6634829