

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403862228

Date Received:  
07/23/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:  
2 of 3 CAs from the FIR responded to on this Form  
2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-3779  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
ERIN JOSEPH	970-515-1169	ECMCInspections@Oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714201280  
Inspection Date: 07/12/2024 FIR Submit Date: 07/12/2024 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 309856

Location Name: LUDWIG H-63N65W Number: 6SWNE County:  
Qtrqtr: SWNE Sec: 6 Twp: 3N Range: 65W Meridian: 6  
Latitude: 40.257954 Longitude: -104.705853

FACILITY - API Number: 05-123-00 Facility ID: 309856

Facility Name: LUDWIG H-63N65W Number: 6SWNE  
Qtrqtr: SWNE Sec: 6 Twp: 3N Range: 65W Meridian: 6  
Latitude: 40.257954 Longitude: -104.705853

CORRECTIVE ACTIONS:

1 CA# 196762

Corrective Action: Comply with 603.o. Date: 08/31/2024

Response: CA COMPLETED Date of Completion: 07/16/2024

Operator Comment: This location is OOS and the vessel doesn't have fluid in it nor does it have any fluids running through it since it has been air gapped. Photos show the well head and separator air gapped per ECMC regulations. Aside from being air gapped, this location falls under the written spill contingency plan.

ECMC Decision:

ECMC  
Representative:

**3** CA# 196764

Corrective Action: Comply with rule 603.o.

Date: 08/31/2024

Response: CA COMPLETED

Date of Completion: 07/16/2024

Operator  
Comment:

This location is OOS and the vessel doesn't have fluid in it nor does it have any fluids running through it since it has been air gapped.  
Photos show the well head and separator air gapped per ECMC regulations.  
Aside from being air gapped, this location falls under the written spill contingency plan.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: \_\_\_\_\_

Title: SR REGULATORY ADVISOR

Date: 7/23/2024 8:14:12 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files