

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/02/2024

Submitted Date:

07/23/2024

Document Number:

713400188

FIELD INSPECTION FORM

Loc ID 312601 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
 Name of Operator: VISION ENERGY LLC
 Address: P O BOX 370
 City: IGNACIO State: CO Zip: 81137

Findings:

- 13 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ENERGY, VISION		pbechtolt@maralexinc.com	
ENERGY, VISION		mrine20@maralexinc.com	
ENERGY, VISION		mollieo@maralexinc.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221999	WELL	SI	05/01/2010	CBM	077-08601	SOUTH SHALE RIDGE 4-13	SI

General Comment:

CECMC Inspection Report Summary

On 7/2/2024 at approximately 12:27, Compliance Inspector Dusty Popejoy conducted an on-site inspection at VISION ENERGY LLC SOUTH SHALE RIDGE-68S98W/13NWNW at Location ID #312601 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Signs/Marker:

- 1) Inaccurate sign at tank battery with a CA date of 8/23/2024.
- 2) No wellhead sign with a CA date of 8/23/2024.
- 3) Tank label inaccurate and missing tank capacity with a CA date of 8/23/2024.

Housekeeping:

- 4) Debris present across entire location with a CA date of 8/23/2024.
- 5) Storage of supplies/equipment on location with a CA date of 8/23/2024.
- 6) Unused equipment on location with a CA date of 8/23/2024.
- 7) Weeds present across entire location with a CA date of 8/23/2024.

Earth berm:

- 8) permeability inadequate due to weed growth with a CA date of 8/23/2024.

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted at wellhead, refer to photos.		
Corrective Action:	Comply with CECMC signage rules.	Date:	08/23/2024
Type	BATTERY		
Comment:	Inaccurate operator information on battery sign, refer to photos.		
Corrective Action:	Comply with CECMC signage rules.	Date:	08/23/2024
Type	TANK LABELS/PLACARDS		
Comment:	Tank label missing volume capacity with inaccurate operator information, refer to photos.		
Corrective Action:	Comply with CECMC labeling rules.	Date:	08/23/2024

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds and undesirable plant species present across entire location, refer to photos.		
Corrective Action:	Comply with CECMC weed control rules.	Date:	08/23/2024
Type	STORAGE OF SUPL		
Comment:	Storage of supplies and equipment on location, refer to photos.		
Corrective Action:	Comply with CECMC storage of supplies/equipment rules.	Date:	08/23/2024
Type	DEBRIS		
Comment:	Debris present across entire location, refer to photos.		
Corrective Action:	Comply with CECMC debris rules.	Date:	08/23/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location includes pump jacks, separator, fiberglass tanks, and other miscellaneous equipment, refer to photos.		
Corrective Action:	Comply with CECMC unused equipment rules.	Date:	08/23/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment:	No
Comment:	<input style="width: 100%;" type="text"/>
<input type="checkbox"/>	Multiple Spills and Releases?

Equipment:		corrective date
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berm permeability is inadequate due to weed growth in berm, refer to photos.			
Corrective Action:	Comply with CECMC weed control rules.			Date: 08/23/2024

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 221999 Type: WELL API Number: 077-08601 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Gravel				
Waddles						
Gravel						
		Compaction				
Compaction						
		Ditches				

Comment: [Light gravel and compaction on location and lease road.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400189	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636156