

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 312598

Date: 7/2/2024



Entrance to location - Photo #03269

Wellhead - Photo #03272

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 312598

Date: 7/2/2024



Pump Jack - Photo #03273



Separator/Meter run - Photo #03274

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 312598

Date: 7/2/2024



Tank battery/Inadequate berm permeability - Photo #03275



Inaccurate company information on battery sign - Photo #03276

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 312598

Date: 7/2/2024



Tank port open entry to wildlife hazard - Photo #03288



Debris - Photo #03292

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 312598

Date: 7/2/2024



Debris - Photo #03294



Debris - Photo #03295

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 312598

Date: 7/2/2024



Debris - Photo #03296



Storage of supplies/equipment - Photo #03297

Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 312598

Date: 7/2/2024



Southwest corner of location - Photo #03290



Southeast corner of location - Photo #03291