

## Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 324270

Date: 7/2/2024



Entrance to location - Photo #03299



Location - Photo #03307



## Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 324270

Date: 7/2/2024



Wellhead - Photo #03300



Pump Jack - Photo #03301



## Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 324270

Date: 7/2/2024



Separator/Meter run - Photo #03302



Tank Battery/Berm permeability is inadequate due to weed growth in berm - Photo #03305



## Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 324270

Date: 7/2/2024



Northeast corner of location - Photo #03308



Northwest corner of location - Photo #03309



## Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 324270

Date: 7/2/2024



Debris - Photo #03310



Debris - Photo #03311



## Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 324270

Date: 7/2/2024



Debris - Photo #03312



Debris - Photo #03313

## Inspection Photos

Location: Vision Energy LLC South Shale Ridge-68S98W/14NENE

Location ID: 324270

Date: 7/2/2024



Debris - Photo #03314

