

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/02/2024

Submitted Date:

07/23/2024

Document Number:

713400190

FIELD INSPECTION FORM

Loc ID 312598 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ENERGY, VISION		mollieo@maralexinc.com	
ENERGY, VISION		pbechtolt@maralexinc.com	
ENERGY, VISION		mrine20@maralexinc.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221992	WELL	SI	04/01/2010	CBM	077-08594	SOUTH SHALE RIDGE 1-14	SI

General Comment:

CECMC Inspection Report Summary

On 7/2/2024 at approximately 14:31, Compliance Inspector Dusty Popejoy conducted an on-site inspection at VISION ENERGY LLC SOUTH SHALE RIDGE-68S98W/14NENE at Location ID #312598 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Signs/Marker:

- 1) Inaccurate operator information on tank battery sign with a CA date of 8/23/2024
- 2) Inaccurate operator information on wellhead sign with a CA date of 8/23/2024

Tank Battery:

- 3) Tank port open entry to wildlife with a CA date of 8/2/2024

Earth Berm:

- 4) Berm permeability is inadequate due to weed growth in berm with a CA date of 8/23/2024

Housekeeping:

- 5) Debris on location with a CA date of 8/23/2024
- 6) Storage of supplies/equipment on location with a CA date of 8/23/2024
- 7) Weeds and undesirable plant species present across entire location with a CA date of 8/23/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Inaccurate operator information on battery sign, refer to photos.		
Corrective Action:	Comply with CECMC signage rules.		Date: 08/23/2024
Type	WELLHEAD		
Comment:	Inaccurate operator information on wellhead sign, refer to photos.		
Corrective Action:	Comply with CECMC signage rules.		Date: 08/23/2024
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Stored trailers/equipment on location, refer to photos.		
Corrective Action:	Comply with CECMC storage of supplies/equipment rules.		Date: 08/23/2024
Type	DEBRIS		
Comment:	Debris on location, refer to photos		
Corrective Action:	Comply with CECMC debris rules.		Date: 08/23/2024
Type	WEEDS		
Comment:	Weeds and undesirable plant species present across entire location, refer to photos.		
Corrective Action:	Comply with CECMC weed control rules.		Date: 08/23/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:	Tank port open entry to wildlife, refer to photos.				
Corrective Action:	Comply with CECMC wildlife rules.				Date: 08/02/2024

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berm permeability is inadequate due to weed growth in berm, refer to photots.			
Corrective Action:	Comply with CECMC weed control rules.			Date: 08/23/2024

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 221992 Type: WELL API Number: 077-08594 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
Waddles						
		Ditches				
Compaction						
Rip Rap						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400191	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636218