

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2024

Submitted Date:

07/23/2024

Document Number:

713400192**FIELD INSPECTION FORM**Loc ID 324270 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		pbechtolt@maralexinc.com	
ENERGY, VISION		mollieo@maralexinc.com	
ENERGY, VISION		mrine20@maralexinc.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266869	WELL	SI	09/01/2009	CBM	045-09853	SOUTH SHALE RIDGE 1-14H	SI

**General Comment:****CECMC Inspection Report Summary**

On 7/2/2024 at approximately 15:00, Compliance Inspector Dusty Popejoy conducted an on-site inspection at VISION ENERGY LLC SOUTH SHALE RIDGE-68S98W/14NENE at Location ID # 324270 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

**Signs/Marker:**

1) Tank label does not meet required information with a CA date of 8/23/2024

**Housekeeping:**

2) Weeds and undesirable plant species present across entire location with a CA date of 8/23/2024

3) Debris on location with a CA date of 8/23/2024

**Earth Berm:**

4) Berm permeability is inadequate due to weed growth in berm with a CA date of 8/23/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label does not meet required information.		
Corrective Action:	Comply with CECMC labeling rules.	Date:	08/23/2024

Emergency Contact Number:		
Comment:	911/970-858-8550	
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds and undesirable plant species present across entire location, refer to photos.		
Corrective Action:	Comply with CECMC weed control rules.	Date:	08/23/2024
Type	DEBRIS		
Comment:	Debris present across entire location, refer to photos.		
Corrective Action:	Comply with CECMC debris rules.	Date:	08/23/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1		FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	Berm permeability is inadequate due to weed growth in berm, refer to photos.				
Corrective Action:	Comply with CECMC weed control rules.				Date: 08/23/2024

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	266869	Type:	WELL	API Number:	045-09853	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Last produced August 2009. Last MIT performed November 2021.									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						
Waddles						
Berms						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400193	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636219">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636219</a>