

Inspection Photos

Location: TEP Rocky Mountain LLC Williams-67S96W/35SWNW

Location ID: 334409

Date: 7/9/2024



Entrance to location - Photo #03379



Wellheads - Photo #03380

Inspection Photos

Location: TEP Rocky Mountain LLC Williams-67S96W/35SWNW

Location ID: 334409

Date: 7/9/2024



Separators - Photo #03382



Needs moved to tank battery - Photo #03384

Inspection Photos

Location: TEP Rocky Mountain LLC Williams-67S96W/35SWNW

Location ID: 334409

Date: 7/9/2024



Jul 9, 2024 at 10:27:28 AM
+39.394463,-108.084683 ±4.59m

Tank battery/Missing battery sign - Photo #03385



Jul 9, 2024 at 10:36:17 AM
+39.394528,-108.084558 ±4.72m
Parachute

Holes in containment liner - Photo #03398

Inspection Photos

Location: TEP Rocky Mountain LLC Williams-67S96W/35SWNW

Location ID: 334409

Date: 7/9/2024



Hole in containment liner - Photo #03406



Hole in containment liner - Photo #03408

Inspection Photos

Location: TEP Rocky Mountain LLC Williams-67S96W/35SWNW

Location ID: 334409

Date: 7/9/2024



Southwest corner of location - Photo #03409



Debris - Photo #03411

Inspection Photos

Location: TEP Rocky Mountain LLC Williams-67S96W/35SWNW

Location ID: 334409

Date: 7/9/2024



Debris - Photo #03412



Debris - Photo #03395