

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2024

Submitted Date:

07/23/2024

Document Number:

713400202

## FIELD INSPECTION FORM

 Loc ID: 324467  
 Inspector Name: Popejoy, Dusty  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 ECMC Operator Number: 10515  
 Name of Operator: GUNNISON ENERGY LLC  
 Address: 1801 BROADWAY #1150  
 City: DENVER State: CO Zip: 80202
**Findings:**

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
Energy, Gunnison		geops@oxbow.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211722	WELL	TA	05/01/2018	GW	051-06044	FEDERAL 21-7	TA

**General Comment:**

## CECMC Inspection Report Summary

On 7/10/2024 at approximately 11:36, Compliance Inspector Dusty Popejoy conducted an on-site inspection at GUNNISON ENERGY LLC FEDERAL-610S90W/21SWNE at Location ID #324467 in Gunnison County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

## Equipment:

1- Open ended piping/wildlife hazard/ available for entry by wildlife with a CA date of 7/30/2024

## Hosekeeping:

2- Multiple places with stained soils and gravel on location with a CA date of 8/2/2024

3- Multiple debris on location with a CA date of 8/2/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-874-7697		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Multiple debris on location, refer to photos.		
Corrective Action:	Comply with CECMC debris rules.		Date: <u>08/02/2024</u>
Type	OTHER		
Comment:	Multiple places with stained soils and gravel on location.		
Corrective Action:	Remove and properly dispose of all stained soils and gravel.		Date: <u>08/02/2024</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Open ended piping/wildlife hazard/ available for entry by wildlife, refer to photos.		
Corrective Action:	Comply with CECMC wildlife rules.		Date: <u>07/30/2024</u>

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 211722 Type: WELL API Number: 051-06044 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Sediment Traps				
Tracking Pad						
		Berms				
		Gravel				
Gravel						
		Rip Rap				
Seeding						
		Compaction				
Berms						
Compaction						
		Ditches				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400203	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636315">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636315</a>