

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2024

Submitted Date:

07/23/2024

Document Number:

714201305

FIELD INSPECTION FORM

Loc ID 437468 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437470	WELL	PR	01/01/2024	OW	123-39549	Heartland State G36-75-1HN	PR
437471	WELL	PR	08/01/2020	OW	123-39550	Heartland State H01-74-1HNX	PR
437472	WELL	PR	08/01/2020	OW	123-39551	Heartland G25-73-1HN	PR
437473	WELL	PR	08/01/2020	OW	123-39552	Heartland State H01-73-1HN	PR
437474	WELL	PR	08/01/2023	OW	123-39553	Heartland State C31-79-1HN	PR
437475	WELL	PR	08/01/2023	OW	123-39554	Heartland C31-78-1HN	PR
437476	WELL	SI	03/01/2023	OW	123-39555	Heartland C30-79-1HN	SI
437477	WELL	PR	08/01/2023	OW	123-39556	Heartland C30-79HN	PR
437478	WELL	PR	08/01/2023	OW	123-39557	Heartland G25-72-1HN	PR

General Comment:

[THIS IS A WELLHEAD INSPECTION.](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 9		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 437470 Type: WELL API Number: 123-39549 Status: PR Insp. Status: PR

Producing Well

Comment: PR; Valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/30/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 34 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437471 Type: WELL API Number: 123-39550 Status: PR Insp. Status: PR

Producing Well

Comment: PR; Valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/18/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437472 Type: WELL API Number: 123-39551 Status: PR Insp. Status: PR

Producing Well

Comment: PR; Valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/13/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 23 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437473 Type: WELL API Number: 123-39552 Status: PR Insp. Status: PR

Producing Well

Comment: PR; Valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/25/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437474 Type: WELL API Number: 123-39553 Status: PR Insp. Status: PR

Producing Well

Comment: PR; Valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/09/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437475 Type: WELL API Number: 123-39554 Status: PR Insp. Status: PR

Producing Well

Comment: PR; Valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/03/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437476 Type: WELL API Number: 123-39555 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; valves appears to be in the closed position.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 05/29/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437477 Type: WELL API Number: 123-39556 Status: PR Insp. Status: PR

Producing Well

Comment: PR; Valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/17/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437478 Type: WELL API Number: 123-39557 Status: PR Insp. Status: PR

Producing Well

Comment: PR; Valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/17/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Routine inspection. Weather Conditions: Sunny, dry ground	santistb	07/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201306	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636320