

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2024

Submitted Date:

07/24/2024

Document Number:

714201313**FIELD INSPECTION FORM**Loc ID 449991 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email   | Comment                         |
|--------------|-------|---|---------------------------------|
| ,            |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name            | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 449983      | WELL | PR     | 01/03/2022  | OW         | 123-44602 | Centennial State G34-666 | PR          |
| 449986      | WELL | PR     | 01/01/2024  | OW         | 123-44604 | Centennial State G34-675 | PR          |

**General Comment:**[THIS IS A WELLHEAD INSPECTION.](#)

|  |          |        |  |                 |
|--|----------|--------|--|-----------------|
| Location   |          |        |  |                 |
| Overall Good: <input checked="" type="checkbox"/>      |          |        |  |                 |
| <b>Signs/Marker:</b>                                   |          |        |  |                 |
| Type   | WELLHEAD |        |  |                 |
| Comment:   | adequate |        |  |                 |
| Corrective Action:                                     |          |        |  | Date:           |
| Emergency Contact Number:                              |          |        |  |                 |
| Comment:   |          |        |  |                 |
| Corrective Action:                                     |          |        |  | Date: _____     |
| Overall Good: <input checked="" type="checkbox"/>      |          |        |  |                 |
| <b>Spills:</b>   |          |        |  |                 |
| Type   | Area     | Volume |  |                 |
| In Containment: No                                     |          |        |  |                 |
| Comment:   |          |        |  |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |          |        |  |                 |
| <b>Fencing/:</b>                                       |          |        |  |                 |
| Type   | WELLHEAD |        |  |                 |
| Comment:   | panel    |        |  |                 |
| Corrective Action:                                     |          |        |  | Date:           |
| <b>Equipment:</b>                                      |          |        |  |                 |
|  |          |        |  | corrective date |
| Type: Bradenhead                                       | # 2      |        |  |                 |
| Comment:   |          |        |  |                 |
| Corrective Action:                                     |          |        |  | Date:           |
| Type: Plunger Lift                                     | # 2      |        |  |                 |
| Comment:   |          |        |  |                 |
| Corrective Action:                                     |          |        |  | Date:           |
| <b>Venting:</b>  |          |        |  |                 |
| Yes/No   | NO       |        |  |                 |
| Comment:   |          |        |  |                 |
| Corrective Action:                                     |          |        |  | Date:           |
| <b>Flaring:</b>  |          |        |  |                 |
| Type   |          |        |  |                 |
| Comment:   |          |        |  |                 |
| Corrective Action:                                     |          |        |  | Date:           |
|  |          |        |  |                 |

| Inspected Facilities   |        |  |      |                        |           |             |    |               |    |
|--|--------|--|------|------------------------|-----------|-------------|----|---------------|----|
| Facility ID:   | 449983 | Type:  | WELL | API Number:            | 123-44602 | Status:     | PR | Insp. Status: | PR |
| Producing Well   |        |  |      |                        |           |             |    |               |    |
| Comment:   |        | PR; it appears the valves are in an open position. |      |                        |           |             |    |               |    |
| Corrective Action:   |        |  |      |                        |           |             |    | Date:         |    |
| BradenHead   |        |  |      |                        |           |             |    |               |    |
| Date of Last Brhd Test:  |        | 02/01/2024   |      | Annual Brhd Completed? |           | Yes         |    |               |    |
| Last Brhd Test Results   |        | Initial Surf Csg Pressure:                         |      | -1                     |           | Fluid Type: |    |               |    |
|  |        | End Surf Csg Pressure:                             |      | 0                      |           |             |    |               |    |
| Comment:   |        |  |      |                        |           |             |    |               |    |
| Corrective Action:   |        |  |      |                        |           |             |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |  |      |                        |           |             |    |               |    |
| Facility ID:   | 449986 | Type:  | WELL | API Number:            | 123-44604 | Status:     | PR | Insp. Status: | PR |
| Producing Well   |        |  |      |                        |           |             |    |               |    |
| Comment:   |        | PR; it appears the valves are in an open position. |      |                        |           |             |    |               |    |
| Corrective Action:   |        |  |      |                        |           |             |    | Date:         |    |
| BradenHead   |        |  |      |                        |           |             |    |               |    |
| Date of Last Brhd Test:  |        | 04/06/2024   |      | Annual Brhd Completed? |           | Yes         |    |               |    |
| Last Brhd Test Results   |        | Initial Surf Csg Pressure:                         |      | 1                      |           | Fluid Type: |    |               |    |
|  |        | End Surf Csg Pressure:                             |      | 0                      |           |             |    |               |    |
| Comment:   |        |  |      |                        |           |             |    |               |    |
| Corrective Action:   |        |  |      |                        |           |             |    | Date:         |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |  |      |                        |           |             |    |               |    |

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

|  |          |            |
|--|----------|------------|
| Comment  | User     | Date       |
| <a href="#">Routine Inspection.</a><br><a href="#">Weather Conditions: sunny, dry ground</a> | santistb | 07/24/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

|              |             |   |
|--------------|-------------|---|
| Document Num | Description | URL   |
| 714201314    | Photos      | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6637450">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6637450</a> |