

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
07/25/2024  
Submitted Date:  
07/25/2024  
Document Number:  
714201325

**FIELD INSPECTION FORM**

Loc ID 423662 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email   | Comment                         |
|--------------|-------|---|---------------------------------|
| ,            |       | rbucogccinspectionreports@chevron.onmicrosoft.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 423660      | WELL | SI     | 07/01/2022  | OW         | 123-33661 | SHELTON 27-2  | SI          |

**General Comment:**

[THIS IS A WELLHEAD/BATTERY INSPECTION.](#)

**Location**

Overall Good:

| <b>Signs/Marker:</b> |  |       |            |
|----------------------|--|-------|------------|
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             | two tanks signage no longer legible (capacity, contents). See attached photos. |       |            |
| Corrective Action:   | Comply with Ruel 605.h.  | Date: | 08/25/2024 |
| Type                 | BATTERY  |       |            |
| Comment:             | Adequate   |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             | Adequate   |       |            |
| Corrective Action:   |  | Date: |            |

|                                  |                      |  |             |
|----------------------------------|----------------------|--|-------------|
| <b>Emergency Contact Number:</b> |                      |  |             |
| Comment:                         | <input type="text"/> |  |             |
| Corrective Action:               | <input type="text"/> |  | Date: _____ |

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |
|                |      |        |  |

In Containment: No

Comment:

Multiple Spills and Releases?

| <b>Fencing/:</b>   |              |       |  |
|--------------------|--------------|-------|--|
| Type               | WELLHEAD     |       |  |
| Comment:           | panel        |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | wire         |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | wire         |       |  |
| Corrective Action: |              | Date: |  |

| <b>Equipment:</b>                 |     |       | corrective date |
|-----------------------------------|-----|-------|-----------------|
| Type: Bird Protectors             | # 4 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Emission Control Device     | # 2 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 2 |       |                 |

|                     |     |  |       |
|---------------------|-----|--|-------|
| Comment:            |     |  |       |
| Corrective Action:  |     |  | Date: |
| Type: Gas Meter Run | # 2 |  |       |
| Comment:            |     |  |       |
| Corrective Action:  |     |  | Date: |
| Type: Plunger Lift  | # 1 |  |       |
| Comment:            |     |  |       |
| Corrective Action:  |     |  | Date: |
| Type: Bradenhead    | # 1 |  |       |
| Comment:            |     |  |       |
| Corrective Action:  |     |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | PBV FIBERGLASS |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares containment with other tanks. |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| OTHER              | 2 | OTHER    | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  | UNKNOWN  |  |
| Other (Capacity) | UNKNOWN  |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 423660 Type: WELL API Number: 123-33661 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; Form 6A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 02/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p>ECMC Inspection Report Summary<br/>                     WEATHER CONDITIONS: sunny, dry ground.<br/>                     On Thursday, July 25, 2024 at approximately 11:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at SHELTON 27-2 (Noble Energy, Inc.), at location ID: 423662 in WELD COUNTY, Colorado.<br/>                     While there, I observed shut in facility.<br/>                     During this inspection the following possible compliance issues were observed:<br/>                     1. It appears the contents and capacity are no longer legible on two tanks. Comply with Rule 605.h. (Corrective Action Date: August 25, 2024) See attached photo #4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/>                     This is a summary of inspection report.</p> | santistb | 07/25/2024 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 714201326    | Photos      | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639018">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639018</a> |