

WGS84 ±15ft 40.10334, -104.96802 ft ±12ft 4942 °T ±13 SW209



Johnson
© 22-Jul-24 02:47:41 PM
ECMC Environmental Inspection

**ECMC
Environmental
Field Inspection**



Weeds, torn/downed fencing, water within open excavation, inadequate BMPs to control runoff into open excavation

WGS84 ±15ft 40.10335, -104.96802 ft ±12ft 4942 °T ±13 SW242



Johnson
© 22-Jul-24 02:47:43 PM
ECMC Environmental Inspection

**ECMC
Environmental
Field Inspection**



Weeds, torn/downed fencing, water within open excavation, inadequate BMPs to control runoff into open excavation, inadequate BMPs for stockpiled E&P waste, runoff from open excavation and E&P waste stockpile.



Weeds, torn/downed fencing, debris/trash (torn fencing).



Weeds, debris/trash, stained soil, poor housekeeping




Weeds, debris/trash, stained soil, poor housekeeping





WGS84 ±16ft 40.10379, -104.96826 Δ ft ±11ft 4941 \circ , T ±12 NE50



Debris/trash/unused equipment (pieces of flowline/piping and fittings, trash)

Excavation at wellhead has been backfilled.

ECMC
Environmental
Field Inspection



Johnson
© 22-Jul-24 02:49:33 PM
ECMC Environmental Inspection

Weeds, debris/trash, stained soil, poor housekeeping

WGS84 ±16ft 40.10379, -104.96826 Δ ft ±11ft 4941 \circ , T ±12 NE18



ECMC
Environmental
Field Inspection




Johnson
© 22-Jul-24 02:49:35 PM
ECMC Environmental Inspection

Weeds, debris/trash, stained soil, poor housekeeping



Soil at wellhead





Debris/trash/unused equipment, poor housekeeping






Debris/trash/unused equipment, poor housekeeping




Ripple marks from runoff
















Weeds, inadequate BMPs










Inadequate BMPs




Inadequate BMPs



Inadequate BMPs, weeds, downed fencing



Inadequate BMPs, weeds



Inadequate BMPs



Inadequate BMPs, weeds, water overflowing from open excavation



Inadequate BMPs, weeds, water overflowing from open excavation



Inadequate BMPs, weeds, runoff from E&P waste stockpile



Inadequate BMPs, weeds, water overflowing from open excavation, downed fencing



Inadequate BMPs, weeds, water overflowing from open excavation



Failed/Inadequate BMPs



Johnson
© 22-Jul-24 02:57:43 PM
ECMC Environmental Inspection
Failed/Inadequate BMPs, weeds



Weeds, 100-year Floodplain



Weeds, failed/inadequate BMPs, 100-year floodplain



WGS84
±16ft

40.10298, -104.96817

ft
±11ft

4943

°T
±12


NW326

**ECMC
Environmental
Field Inspection**



Johnson
© 22-Jul-24 02:58:29 PM
ECMC Environmental Inspection

Weeds, failed/inadequate BMPs, 100-year floodplain



WGS84
±16ft

40.10287, -104.96809

ft
±11ft

4944

°T
±12

E86

KPK
K.P. KAUFFMAN COMPANY, INC.
Johnson #1 & 2 Battery
SW Section 26, T2N, R66W
Johnson County
688 WCR 13
781-832-7822

**ECMC
Environmental
Field Inspection**



Johnson
© 22-Jul-24 02:58:53 PM
ECMC Environmental Inspection

Weeds, faded signage



Weeds, missing/faded placards

ECMC
Environmental
Field Inspection



Weeds

ECMC
Environmental
Field Inspection





Weeds, unused equipment



Weeds, unused equipment, trash/debris, staining

WGS84 ±16ft 40.10255, -104.96774 Δ ft ±11ft 4945 \triangle °,T ±12 NW304



**ECMC
Environmental
Field Inspection**



Johnson
© 22-Jul-24 03:00:24 PM
ECMC Environmental Inspection

Weeds

WGS84 ±16ft 40.10285, -104.96780 Δ ft ±11ft 4951 \triangleleft °,T ±12 W277



**ECMC
Environmental
Field Inspection**



Johnson
© 22-Jul-24 03:01:01 PM
ECMC Environmental Inspection

Weeds

WGS84 ±16ft 40.10285, -104.96780 Δ ft ±11ft 4951 \triangle °,T ±12 NW308



ECMC
Environmental
Field Inspection



Johnson
© 22-Jul-24 03:01:05 PM
ECMC Environmental Inspection
Weeds, downed fencing

WGS84 ±16ft 40.10315, -104.96798 Δ ft ±11ft 4946 \triangle °,T ±12 W263



ECMC
Environmental
Field Inspection



Johnson
© 22-Jul-24 03:01:46 PM
ECMC Environmental Inspection
Weeds

WGS84 ±16ft 40.10320, -104.96800 Δ ft ±11ft 4946 Δ °,T ±12 NW292



**ECMC
Environmental
Field Inspection**



Johnson
© 22-Jul-24 03:01:58 PM
ECMC Environmental Inspection

Weeds, failed/inadequate BMPs,downed/torn fencing, water overflowing from open excavation and stockpiled E&P waste, 100-year floodplain

WGS84 ±16ft 40.10321, -104.96800 Δ ft ±11ft 4947 Δ °,T ±12 NW312



**ECMC
Environmental
Field Inspection**



Johnson
© 22-Jul-24 03:02:00 PM
ECMC Environmental Inspection

Weeds, failed/inadequate BMPs,downed/torn fencing, water overflowing from open excavation and stockpiled E&P waste, 100-year floodplain



Weeds, inadequate BMPs,downed/torn fencing, open excavation





WGS84 ±15ft 40.10330, -104.96810

ft ±12ft 4950

°T ±18 SE132

ECMC
Environmental
Field Inspection



Johnson
© 22-Jul-24 04:14:44 PM
ECMC Environmental Inspection



WGS84 ±15ft 40.10330, -104.96810

ft ±12ft 4950

°T ±18 S187

ECMC
Environmental
Field Inspection



Johnson
© 22-Jul-24 04:14:47 PM
ECMC Environmental Inspection



ECMC Excavation water sample



ECMC Outside Excavation water sample



Gray/White stained soil




Gray/White stained soil




Gray/White stained soil outside fenced in work area



Gray/White stained soil outside fenced in work area



Gray/White stained soil outside fenced in work area



ECMC Outside Fence water sample