



Site overview; excavation over-topped with stormwater and groundwater, weeds, inadequate BMPs.



Open excavation filled with water.

WGS84 ±15ft 40.10336, -104.96811  $\Delta$  ft ±12ft 4948  $\Delta$  °, T ±13 NW289



**ECMC**  
**Environmental**  
**Field Inspection**



Johnson 1  
© 23-Jul-24 08:16:22 AM  
ECMC Environmental Inspection

Contaminated Soil (E&P Waste) Stockpile with inadequate BMPs.

WGS84 ±15ft 40.10336, -104.96811  $\Delta$  ft ±12ft 4948  $\Delta$  °, T ±13 S193



**ECMC**  
**Environmental**  
**Field Inspection**



Johnson 1  
© 23-Jul-24 08:16:27 AM  
ECMC Environmental Inspection

Open excavation filled with water (groundwater and surface water). Inadequate BMPs to control run-in/run-off around the excavation.



Crews returned to continue hydrovacuuming water from open excavation (Second truckload). Inadequate stormwater BMPs.



Open excavation filled with water (groundwater and surface water). Inadequate BMPs to control run-in/run-off around the excavation.



Publicly accessible walking path, inadequate BMPs to control runoff.



Excavation filled with surface and groundwater; note flowline bend visible in excavation, field personnel indicated additional repairs will be conducted once excavation drawn down.


WGS84 ±12ft 40.10333, -104.96812  $\Delta$  ft ±10ft 4944  $\Delta$  °T ±12 SW242



**ECMC  
Environmental  
Field Inspection** 

Johnson 1  
© 23-Jul-24 09:15:02 AM  
ECMC Environmental Inspection

Excavation filled with surface and groundwater; note flowline bend visible in excavation, field personnel indicated additional repairs will be conducted once excavation drawn down.




WGS84 ±15ft 40.10332, -104.96810  $\Delta$  ft ±12ft 4946  $\Delta$  °T ±12 W280

**ECMC  
Environmental  
Field Inspection** 

Johnson 1  
© 23-Jul-24 09:15:08 AM  
ECMC Environmental Inspection

Soil sample location



Weed growth on sidewall of excavation