

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2024

Submitted Date:

07/25/2024

Document Number:

697009822

**FIELD INSPECTION FORM**

Loc ID 319097 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                    | Comment |
|--------------|-------|--------------------------|---------|
|              |       | cogccinspection@pdce.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 242878      | WELL | PR     | 02/01/2021  | GW         | 123-10669 | JOHNSON 17-1  | PR          |

**General Comment:**

This is a routine audit. Any corrective actions from previous audits that have not been addressed are still applicable. There were no operator personnel on location at the time of this field audit.

**Location**

Overall Good:

**Signs/Marker:**

|                    |  |       |            |
|--------------------|--|-------|------------|
|                    | Type WELLHEAD                            |       |            |
| Comment:           | Sign is not posted, see attached photos. |       |            |
| Corrective Action: | Install sign to comply with Rule 605.d.  | Date: | 09/30/2024 |

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |               |       |  |
|--------------------|---------------|-------|--|
|                    | Type WELLHEAD |       |  |
| Comment:           | Panel         |       |  |
| Corrective Action: |               | Date: |  |

**Equipment:**

|                    |   | #   |  | corrective date |
|--------------------|---|-----|--|-----------------|
| Type: Bradenhead   |   | # 1 |  |                 |
| Comment:           | Bradenhead valve is exposed at surface. |     |  |                 |
| Corrective Action: |   |     |  | Date:           |
| Type: Flow Line    |   | # 1 |  |                 |
| Comment:           |   |     |  |                 |
| Corrective Action: |   |     |  | Date:           |
| Type: Plunger Lift |   | # 1 |  |                 |
| Comment:           |   |     |  |                 |
| Corrective Action: |   |     |  | Date:           |

**Tanks and Berms:**

| Contents           | #                    | Capacity | Type                | Tank ID | SE GPS |
|--------------------|----------------------|----------|---------------------|---------|--------|
|                    |                      |          | CENTRALIZED BATTERY |         |        |
| Comment:           | Tank battery #447372 |          |                     |         |        |
| Corrective Action: |                      |          |                     |         | Date:  |

**Paint**

|                  |  |  |  |
|------------------|--|--|--|
| Condition        | <input style="width: 90%; height: 20px;" type="text"/> |  |  |
| Other (Content)  |  |  |  |
| Other (Capacity) |  |  |  |
| Other (Type)     |  |  |  |

| <b>Berms</b>       |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| <b>Venting:</b>    |    |  |  |       |
|--------------------|----|--|--|-------|
| Yes/No             | NO |  |  |       |
| Comment:           |    |  |  |       |
| Corrective Action: |    |  |  | Date: |

| <b>Flaring:</b>    |  |  |  |       |
|--------------------|--|--|--|-------|
| Type               |  |  |  |       |
| Comment:           |  |  |  |       |
| Corrective Action: |  |  |  | Date: |

**Inspected Facilities**

Facility ID: 242878 Type: WELL API Number: 123-10669 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 01/19/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 28 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User      | Date       |
|--|-----------|------------|
| <p>COGCC Inspection Report Summary<br/>                     On Thursday 7/25/2024 at approximately 12:05 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Johnson 17-1 location #319097 in Weld County, Colorado.<br/>                     While there, I observed that the wellhead sign was not posted. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 9/30/2024.<br/>                     A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.<br/>                     This is a summary of the inspection report.</p> | petersont | 07/25/2024 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697009823    | Photo       | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639270">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639270</a> |